364 Halifax Street ADELAIDE SA 5000

Duty Phone: 0417 820 911



Airborne Asbestos Dust Monitoring Report

Date Friday, 29 April 2022

Removalist Old Red Brick Company

Site Address 167 William Street BEVERLEY &

25-29 Whicker Road GILLMAN

DEMS Job Number 2203175

Asbestos Assessor I. Langholz: AAL No. 560603

				On		Ave.	
Sample		Internal		Time	Duration	Flow	Dust Conc.
Number	Type	External	Sample Location	h:min	minutes	ml/min	Fibres/ml
			BEVERLEY				
151	В	External	Northeast of East stockpile	7:12	556	2000	<0.01
152	В	External	Northwest of East stockpile	7:13	556	2000	<0.01
153	В	External	Southeast of East stockpile	7:14	557	2000	<0.01
154	В	External	Adjacent entrance gate	7:16	556	2000	<0.01
			GILLMAN				
155	В	External	Slab between south containers	6:40	615	2000	<0.01
156	В	External	South of dump site	6:42	614	2000	<0.01
157	В	External	West of dump site	6:43	615	2000	<0.01
158	В	External	North of work zone	6:45	614	2000	<0.01

Type: B Background monitoring

Method used: National Occupational Health and Safety Commission

Guidance Note on the Membrane Filter Method for Estimating

Airborne Asbestos Dust.

Note: A dust concentration of <0.01 is the lowest reportable level permitted for

Printed: 29/04/2022

the membrane filter method. All levels were well below this concentration.

Worksafe Australia exposure limit for airborne asbestos = 0.1 fibres

per millilitre of air.