

364 Halifax Street  
ADELAIDE SA 5000  
Duty Phone: 0417 820 911



## Airborne Asbestos Dust Monitoring Report

**Date** Wednesday, 6 April 2022

**Removalist** Old Red Brick Company

**Site Address** 167 William Street BEVERLEY  
25-29 Whicker Road GILLMAN

**DEMS Job Number** 2203175

**Asbestos Assessor** R. Menzel: AAL No. 740174

Sample Number	Type	Internal External	Sample Location	On Time h:min	Duration minutes	Ave. Flow ml/min	Dust Conc. Fibres/ml
			<b>Beverley Site</b>				
49	B	External	Northeast of East stockpile	6:57	568	1500	<0.01
50	B	External	Northwest of East stockpile	6:59	568	1500	<0.01
51	B	External	Southwest of East stockpile	7:01	568	1500	<0.01
52	B	External	Southeast of East stockpile	7:03	568	1500	<0.01
			<b>Gillman Site</b>				
53	B	External	Slab between south containers	7:23	569	1500	<0.01
54	B	External	South of dump site	7:26	569	1500	<0.01
55	B	External	West of dump site	7:28	569	1500	<0.01
56	B	External	Adjacent North fence water tap	7:31	569	1500	<0.01

**Type:** B Background monitoring

**Method used:** National Occupational Health and Safety Commission  
*Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Dust.*

**Note:** A dust concentration of <0.01 is the lowest reportable level permitted for the membrane filter method. All levels were well below this concentration.

Worksafe Australia exposure limit for airborne asbestos = 0.1 fibres per millilitre of air.