

364 Halifax Street
ADELAIDE SA 5000
Duty Phone: 0417 820 911



Airborne Asbestos Dust Monitoring Report

Date Wednesday, 11 May 2022

Removalist Old Red Brick Company

Site Address 167 William Street BEVERLEY

DEMS Job Number 2203175

Asbestos Assessor I. Langholz: AAL No. 560603

Sample Number	Type	Internal External	Sample Location	On Time h:min	Duration minutes	Ave. Flow ml/min	Dust Conc. Fibres/ml
			BEVERLEY				
223	B	External	Northwest of East stockpile	7:31	456	2000	<0.01
224	B	External	Northeast of East stockpile	7:28	462	2000	<0.01
225	B	External	Southeast of East stockpile	7:32	459	2000	<0.01
226	B	External	Adjacent entrance gate	7:34	461	2000	<0.01

Type: B Background monitoring

Method used: National Occupational Health and Safety Commission
Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Dust.

Note: A dust concentration of <0.01 is the lowest reportable level permitted for the membrane filter method. All levels were well below this concentration.

Worksafe Australia exposure limit for airborne asbestos = 0.1 fibres per millilitre of air.