364 Halifax Street ADELAIDE SA 5000

Duty Phone: 0417 820 911



## **Airborne Asbestos Dust Monitoring Report**

Date Tuesday, 26 April 2022

Removalist Old Red Brick Company

Site Address 167 William Street BEVERLEY &

25-29 Whicker Road GILLMAN

**DEMS Job Number** 2203175

Asbestos Assessor I. Langholz: AAL No. 560603

				On		Ave.	
Sample		Internal		Time	Duration	Flow	Dust Conc.
Number	Type	External	Sample Location	h:min	minutes	ml/min	Fibres/ml
			BEVERLEY				
127	В	External	Northeast of East stockpile	7:25	553	2000	<0.01
128	В	External	Northwest of East stockpile	7:27	552	2000	<0.01
129	В	External	Southeast of East stockpile	7:29	551	2000	<0.01
130	В	External	Adjacent entrance gate	7:30	551	2000	<0.01
			GILLMAN				
131	В	External	Slab between south containers	7:02	603	2000	<0.01
132	В	External	South of dump site	7:05	602	2000	<0.01
133	В	External	West of dump site	7:06	602	2000	<0.01
134	В	External	North of work zone	7:08	602	2000	<0.01

**Type:** B Background monitoring

Method used: National Occupational Health and Safety Commission

Guidance Note on the Membrane Filter Method for Estimating

Airborne Asbestos Dust.

**Note:** A dust concentration of <0.01 is the lowest reportable level permitted for

Printed: 26/04/2022

the membrane filter method. All levels were well below this concentration.

Worksafe Australia exposure limit for airborne asbestos = 0.1 fibres

per millilitre of air.