364 Halifax Street ADELAIDE SA 5000

Duty Phone: 0417 820 911



Airborne Asbestos Dust Monitoring Report

Date Thursday, 14 April 2022

Removalist Old Red Brick Company

Site Address 25-29 Whicker Road GILLMAN

DEMS Job Number 2203175

Asbestos Assessor I. Langholz: AAL No. 560603

Sample Number	Туре	Internal External	Sample Location	On Time h:min	Duration minutes	Ave. Flow ml/min	Dust Conc. Fibres/ml
			GILLMAN				
93	В	External	Slab between south containers	6:46	604	1500	<0.01
94	В	External	South of dump site	6:47	607	1500	<0.01
95	В	External	West of dump site	6:49	606	1500	<0.01
96	В	External	North of screen operation	6:50	607	1500	<0.01

Type: B Background monitoring

Method used: National Occupational Health and Safety Commission

Guidance Note on the Membrane Filter Method for Estimating

Airborne Asbestos Dust.

Note: A dust concentration of <0.01 is the lowest reportable level permitted for

Printed: 14/04/2022

the membrane filter method. All levels were well below this concentration.

Worksafe Australia exposure limit for airborne asbestos = 0.1 fibres

per millilitre of air.