364 Halifax Street ADELAIDE SA 5000

Duty Phone: 0417 820 911



## **Airborne Asbestos Dust Monitoring Report**

Date Tuesday, 19 April 2022

Removalist Old Red Brick Company

Site Address 25-29 Whicker Road GILLMAN

**DEMS Job Number** 2203175

Asbestos Assessor I. Langholz: AAL No. 560603

Sample Number	Туре	Internal External	Sample Location	On Time h:min	Duration minutes	Ave. Flow ml/min	Dust Conc. Fibres/ml
			GILLMAN				
97	В	External	Slab between south containers	6:55	596	1500	<0.01
98	В	External	South of dump site	6:57	597	1500	<0.01
99	В	External	West of dump site	6:59	595	1500	<0.01

Type: B Background monitoring

Method used: National Occupational Health and Safety Commission

Guidance Note on the Membrane Filter Method for Estimating

Airborne Asbestos Dust.

**Note:** A dust concentration of <0.01 is the lowest reportable level permitted for

Printed: 19/04/2022

the membrane filter method. All levels were well below this concentration.

Worksafe Australia exposure limit for airborne asbestos = 0.1 fibres

per millilitre of air.