364 Halifax Street ADELAIDE SA 5000

Duty Phone: 0417 820 911



Airborne Asbestos Dust Monitoring Report

Date Friday, 13 May 2022

Removalist Old Red Brick Company

Site Address 167 William Street BEVERLEY &

DEMS Job Number 2203175

Asbestos Assessor R. de Vries: AAL No. 560597

Sample Number	Туре	Internal External	Sample Location BEVERLEY	On Time h:min	Duration minutes	Ave. Flow ml/min	Dust Conc. Fibres/ml
227	В	External	Northwest of East stockpile	7:36	460	1500	<0.01
228	В	External	Northeast of East stockpile	7:37	460	1500	<0.01
229	В	External	Southeast of East stockpile	7:38	460	1500	<0.01
230	В	External	Adjacent entrance gate	7:39	460	1500	<0.01

Type: B Background monitoring

Method used: National Occupational Health and Safety Commission

Guidance Note on the Membrane Filter Method for Estimating

Airborne Asbestos Dust.

Note: A dust concentration of <0.01 is the lowest reportable level permitted for

Printed: 13/05/2022

the membrane filter method. All levels were well below this concentration.

Worksafe Australia exposure limit for airborne asbestos = 0.1 fibres

per millilitre of air.