

364 Halifax Street
ADELAIDE SA 5000
Duty Phone: 0417 820 911



Airborne Asbestos Dust Monitoring Report

Date Tuesday, 12 April 2022
Removalist Old Red Brick Company
Site Address 25-29 Whicker Road GILLMAN
DEMS Job Number 2203175
Asbestos Assessor I. Langholz: AAL No. 560603

Sample Number	Type	Internal External	Sample Location	On Time h:min	Duration minutes	Ave. Flow ml/min	Dust Conc. Fibres/ml
			GILLMAN				
85	B	External	Slab between south containers	7:09	582	1500	<0.01
86	B	External	South of dump site	7:12	581	1500	<0.01
87	B	External	West of dump site	7:03	592	1500	<0.01
88	B	External	North of screen operation	7:14	584	1500	<0.01

Type: B Background monitoring

Method used: National Occupational Health and Safety Commission
Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Dust.

Note: A dust concentration of <0.01 is the lowest reportable level permitted for the membrane filter method. All levels were well below this concentration.

Worksafe Australia exposure limit for airborne asbestos = 0.1 fibres per millilitre of air.