364 Halifax Street ADELAIDE SA 5000

Duty Phone: 0417 820 911



Airborne Asbestos Dust Monitoring Report

Date Monday, 16 May 2022

Removalist Old Red Brick Company

Site Address 167 William Street BEVERLEY &

DEMS Job Number 2203175

Asbestos Assessor I. Langholz: AAL No. 560603

| Sample Number | Туре | Internal External | Sample Location BEVERLEY | On Time h:min | Duration minutes | Ave. Flow ml/min | Dust Conc. Fibres/ml |
|------------------|------|----------------------|-----------------------------|---------------------|---------------------|------------------------|-------------------------|
| 235 | В | External | Northwest of East stockpile | 7:30 | 457 | 1500 | <0.01 |
| 236 | В | External | Northeast of East stockpile | 7:32 | 457 | 1500 | <0.01 |
| 237 | В | External | Southeast of East stockpile | 7:33 | 449 | 1500 | <0.01 |
| 238 | В | External | Adjacent entrance gate | 7:28 | 452 | 1500 | <0.01 |
| | | | | | | | |

Type: B Background monitoring

Method used: National Occupational Health and Safety Commission

Guidance Note on the Membrane Filter Method for Estimating

Airborne Asbestos Dust.

Note: A dust concentration of <0.01 is the lowest reportable level permitted for

Printed: 16/05/2022

the membrane filter method. All levels were well below this concentration.

Worksafe Australia exposure limit for airborne asbestos = 0.1 fibres

per millilitre of air.