364 Halifax Street ADELAIDE SA 5000

Duty Phone: 0417 820 911



## **Airborne Asbestos Dust Monitoring Report**

Date Saturday, 30 April 2022

Removalist Old Red Brick Company

Site Address 167 William Street BEVERLEY &

25-29 Whicker Road GILLMAN

**DEMS Job Number** 2203175

Asbestos Assessor I. Langholz: AAL No. 560603

				On		Ave.	
Sample		Internal		Time	Duration	Flow	Dust Conc.
Number	Type	External	Sample Location	h:min	minutes	ml/min	Fibres/ml
			BEVERLEY				
159	В	External	Northeast of East stockpile	7:06	481	2000	<0.01
160	В	External	Northwest of East stockpile	7:08	480	2000	<0.01
161	В	External	Southeast of East stockpile	7:10	480	2000	<0.01
162	В	External	Adjacent entrance gate	7:11	480	2000	<0.01
			GILLMAN				
163	В	External	Slab between south containers	6:34	546	2000	<0.01
164	В	External	South of dump site	6:35	547	2000	<0.01
165	В	External	West of dump site	6:37	546	2000	<0.01
166	В	External	North of work zone	6:39	546	2000	<0.01

**Type:** B Background monitoring

Method used: National Occupational Health and Safety Commission

Guidance Note on the Membrane Filter Method for Estimating

Airborne Asbestos Dust.

**Note:** A dust concentration of <0.01 is the lowest reportable level permitted for

Printed: 30/04/2022

the membrane filter method. All levels were well below this concentration.

Worksafe Australia exposure limit for airborne asbestos = 0.1 fibres

per millilitre of air.